

**Lock Door at Stockholm, Ström****Facts:**

- Start of the project:

February 1994

- End of the project:

February 1994

- Exact location:

Stockholm Ström

(in the old city centre of Stockholm)

Belgium

- Name client:

City of Stockholm

- Contact person:

/

- Treated surface:

Complete door and parts

- Applied products:

Humidur®

- Extra information:

The application of the Humidur® coating was performed in harsh freezing temperatures.

The lock gate is kept in its original state with Humidur in the old city centre of Stockholm.

Acotec nv



Different views on the coated and protected lock door in Stockholm

