

**Belwind wind farm
Coating Repair**

Acotec nv

**Facts:**

- Description of the project:

Humidur® was used as repair system on offshore wind turbines of the Belwind wind farm. The application was done on St3 prepared surfaces in the splash zone.

Inspection carried out by Belwind after 1 year showed that Humidur® is in excellent condition and shows superior anti-corrosive properties (report available upon request).

- Date:

2014 - 2015

- Name client:

Belwind

- Applied products:

HUMIDUR®



Repairs with Humidur®



Close up Humidur®